

Box CE VC Primary School - Accessibility Plan

	Task	Lead	Timeframe	Success Criteria	Monitoring and Evaluation
Short term	<ol style="list-style-type: none"> 1. To put handrails by the steps in the school garden 2. To improve signage internally and externally around the school, including the car park. 3. To make changes to signage ensuring we have a unisex toilet e.g. disabled toilet and staff toilets in main building 4. To replace blinds in the classrooms in the extension and the headteacher's office 	<p>JF</p> <p>Policy and Curriculum Committee</p>	Completed	<ol style="list-style-type: none"> 1. The steps in the school garden are safer for everyone to use 2. Signage around the school has improved 3. A unisex toilet is available for staff and visitors to use 4. Blinds in classrooms and the h/t's office enable all children to see whiteboards etc. 	<ol style="list-style-type: none"> 1. All steps of more than three steps in the school garden have a handrail 2. Signage in the school carpark has been replaced so that the entrance and exit is clear 3. Unisex signs are in place on staff/visitor toilets 4. Blinds have been installed in classrooms and headteacher's office
Medium Term	<ol style="list-style-type: none"> 1. Level ramped access to the old entrance and at least one additional exit 2. Classroom sinks fitted with lever operated mixer taps 3. Door knobs replaced with lever handles 	<p>JF</p> <p>Policy and Curriculum Committee</p>	2018/19	<ol style="list-style-type: none"> 1. There is easier disabled access to the school 2. Taps and doors can be operated easily by all children 	<p>The gradient of the car park and the position of the railing means that this is not possible and disabled access is through the double doors by the extension.</p> <p>The taps in Ash Class have been replaced with lever taps. There are lever taps in the group room and disabled toilet.</p> <p>All new doors have lever handles, the only ones that don't are original doors in the main part of the school</p>

<p>Long Term</p>	<ol style="list-style-type: none"> 1. Re tarmac the car park and make a designated disabled bay and a pedestrian route marked 2. Consider the installation of a hearing induction loop 3. Consider the installation of a platform lift in the main building on the stairs leading down to the toilets 	<p>JF Policy and Curriculum Committee</p>	<p>2018/19</p>	<ol style="list-style-type: none"> 1. The surface of the car park is even with bays and pedestrian routes clearly labelled 2. The benefits/use v cost of an induction loop and platform lift have been considered 	<p>Completed - Aug 2017</p> <p>July 2019</p>
-------------------------	--	---	-----------------------	---	--